

VEHICLE INSPECTION REPORT

Vehicle

Cab Type

GLEN7

TERBERG YT180

Inspection

Fuel Type

Mileage	Not Showing	Body Style	Tractor Unit		
Year		VIN		Rear Suspension	Air
Reg. date		Colour		Axle Combi	4x2
Details					
		<u>V5</u>	To Follow		
		VAT	Plus VAT		

DAY CAB

^{*}HEAVILY SMOKING, ACCELERATOR REQUIRES ATTENTION, OUTSTANDING RECALL* MOT SHOWS 118,871 MILES 8/9/2025, SINGLE HUB REDUCTION

Tyres			
Tyres NSF			
NSR			
OSF			
OSR			
Spare			

Photos



Diesel













